



Premium VIN Decoder

Report Generated: 03-16-2024



2012 Honda Accord 2.4 LX

VIN: 1HGCP2F49CA092806

STYLE: 2.4 LX 4dr Sedan Automatic

Experience the power and performance of the 2012 Honda Accord 2.4 LX. This reliable sedan is equipped with a 2.4L I-4 177hp engine and a 5-speed automatic transmission with overdrive. Safety is a top priority with 4-wheel anti-lock brakes, side seat mounted airbags, and curtain 1st and 2nd row overhead airbags. Enjoy the comfort of air conditioning and cruise control while driving on 16" steel wheels. With ABS and driveline traction control, as well as electronic stability, you can feel confident on the road. Upgrade your driving experience with the 2012 Honda Accord 2.4 LX.

PRICE

Base Msrp	22,280
Delivery Charges	790
Invoice Price	20,397
Total Price	23,070
Currency	USD

VEHICLE

Epa Classification	Large
Body Type	Sedan
Doors	4

DIMENSIONS

EXTERIOR	
Overall Length	4,950 mm / 194.88 in
Overall Width	1,847 mm / 72.72 in
Max Width Without Mirrors	72.7 in / 1,846.58 mm
Overall Height	1,476 mm / 58.11 in
Track Width Front	62.6 in / 1,590.04 mm
Track Width Rear	62.6 in / 1,590.04 mm
Wheelbase	2,799 mm / 110.2 in
INTERIOR	
Passenger Volume	3,002 l / 106 cu.ft
Trunk Volume	14.7 cu.ft / 416.26 l
Front Head Room	1,052 mm / 41.4 in
Rear Head Room	978 mm / 38.5 in

EXTERIOR	
Front Shoulder Room	1,478 mm / 58.2 in
Rear Shoulder Room	1,433 mm / 56.4 in
Front Leg Room	1,080 mm / 42.5 in
Rear Leg Room	945 mm / 37.2 in
CARGO	
Cargo Volume	416 l / 15 cu.ft
Max Cargo Volume	416 l / 15 cu.ft
WEIGHTS	
Curb Weight Base	3,279 lb / 1,487.07 kg
Towing Capacity	1,001.07 lb / 454 kg
STEERING	
Turning Diameter Curb To Curb	37.7 ft / 11.49 m
Turning Radius Curb To Curb	18.85 ft / 5.75 m
BRAKING	
Front Brake Rotor Dia	11.1 in / 281.94 mm
Rear Brake Rotor Dia	11.1 in / 281.94 mm
WHEELS	
Front Wheel Size	16 x -TBD- in
Rear Wheel Size	16 x -TBD- in
Spare Wheel Size	Compact in
ENGINE	
Engine Size	2.4 l
Horsepower	6,500 rpm / 177 hp
Torque	4,300 rpm / 161 lb.ft
Bore	87 mm / 3.43 in
Stroke	99 mm / 3.9 in
FUEL	
Tank Capacity	18.5 gal / 70.02 l
MPG	
Cruising Range City	425.5 mi
Cruising Range Hwy	629 mi

SPECIFICATIONS

STEERING	
Type	Pwr Rack & Pinion
Overall Ratio	13.1
Turns To Turns Ratio	2.6
BRAKING	

STEERING	
Type	Pwr
Primary Abs System	4-Wheel
Front Disc	Yes
Rear Disc	Yes
ELECTRICAL	
Cold Cranking Capacity Amps	440
SUSPENSIONS	
Front Type	Double wishbone
Front Type Extended	W/Coil Springs
Rear Type	Multi-link
Rear Type Extended	W/Coil Springs
SEATING	
Number Of Seats	5
Max Seating Capacity	5
WHEELS	
Front Wheel Material	Steel
Rear Wheel Material	Steel
Spare Wheel Material	Steel
TIRES	
Front Tire Size	P215/60HR16
Rear Tire Size	P215/60HR16
Spare Tire Size	Compact
Type	All-season
EMISSIONS	
Greenhouse Gas Score	7
Air Pollution Score	7
ENGINE	
Type	Gas I4
Cylinders Configuration	I-4
Displacement	2,400
Drivetype	FWD
Engine Location	Front
Valves	16
Compression	10.5
Block Type	I
Cam Type	DOHC
FUEL	
Type	Gasoline
Grade	Regular unleaded

STEERING**MPG**

Epa City Economy	23
Epa Hwy Economy	34
Epa Combined Economy	27

TRANSMISSION

Type	Automatic
Code	5AT
Number Of Speeds	5
Description	5 speed automatic
First Gear Ratio	2.65
Second Gear Ratio	1.51
Third Gear Ratio	1.03
Fourth Gear Ratio	0.73
Fifth Gear Ratio	0.56
Reverse Gear Ratio	2
Final Drive Axle Ratio	4.44

OEM OPTIONS AND PACKAGES**Engine - Standard**

Name	Engine: 2.4L 16-Valve DOHC i-VTEC I-4
Price	0
Invoice	0
Code	STDEN

Transmissions - Standard

Name	Transmission: Electronic 5-Speed Automatic w/OD
Features	4.44 Axle Ratio
Price	0
Invoice	0
Code	5AT

Wheels - Standard

Name	Wheels: 16" x 6.5" w/Full Covers
Price	0
Invoice	0
Code	STDWL

Tires - Standard

Name	Tires: P215/60R16 94H AS
------	--------------------------

Price	0
Invoice	0
Code	STDTR
Mechanical - Standard	
Name	Partial Zero-Emission Vehicle (PZEV)
Features	PZEV (Partial Zero-Emission Vehicle) models as certified by California Air Resources Board (CARB) are available in California and states that have adopted California Zero-Emission Vehicle regulations.
Price	0
Invoice	0
Code	PZEV
Exterior - Standard	
Name	Monotone Paint Application
Price	0
Invoice	0
Code	PAINT
Seats - Standard	
Name	Front Bucket Seats
Features	Includes driver's seat manual height adjustment.
Price	0
Invoice	0
Code	STDST
Seat Trim - Standard	
Name	Cloth Seat Trim
Price	0
Invoice	0
Code	STDTM
Audio - Standard	
Name	Radio: 160-Watt AM/FM/CD Audio System
Features	Includes 6 speakers, Radio Data System (RDS), MP3/Windows Media Audio (WMA) playback capability, MP3/auxiliary input jack, USB audio interface and Speed-Sensitive Volume Control (SVC).
Price	0
Invoice	0
Code	STDRD

WARRANTIES

Basic Warranty (months/miles)	36/36,000
Corrosion Perforation Warranty (months/miles)	60/0
Powertrain Warranty (months/miles)	60/60,000

STANDARD OPTIONS

Engine	2.4L 16-Valve DOHC i-VTEC I-4
Transmission	Electronic 5-Speed Automatic w/OD
Wheels	16" x 6.5" w/Full Covers
Tires	P215/60R16 94H AS
Monotone Paint Application	
Front Bucket Seats	
Cloth Seat Trim	
Radio	160-Watt AM/FM/CD Audio System

STANDARD FEATURES

2.4l I-4 Engine
5-spd Man W/od Transmission
177 @ 6,500 Rpm Horsepower
161 @ 4,300 Rpm Torque
Front-wheel Drive Type
Abs And Driveline Traction Control
16" Steel Wheels
Front Air Conditioning, Manual
Am/fm Stereo, Seek-scan Radio
Keyfob (all Doors) Remote Keyless Entry
Cloth Seat Trim

FEATURES

INTERIOR FEATURES

Cloth Front Bucket Seats -inc: Driver Manual Height Adjustment, Passenger-side Walk-in Feature
Fold-down Rear Seatback
Driver & Front Passenger Seatback Pockets
Driver & Front Passenger Active Head Restraints
Tilt & Telescopic Steering Column
Illuminated Steering Wheel-mounted Audio & Cruise Controls
Instrumentation W/backlit Gauges -inc: Tachometer, Digital Odometer & (2) Digital Trip Meters
Center Console W/sliding Armrest, Storage Compartments
Cargo Area Light
Dual Illuminated Visor Vanity Mirrors
Lockable Glove Box
Front & Rear Cup Holders
Sunglasses Holder
Floor Mats

INTERIOR FEATURES

Pwr Windows W/driver Auto-up/down

Remote Entry System W/pwr Window Control, Pwr Trunk Release

Rear Window Defroster

Map Lights

Pwr Door Locks W/auto-lock

Remote Trunk Release W/lock

Cruise Control

Remote Fuel Filler Door Release

(2) 12v Pwr Outlets

Immobilizer Theft-deterrent System

Air Conditioning W/air Filtration System

Maintenance Minder System

Security System

Coin Box

Side Door Pockets

EXTERIOR FEATURES

Variable Intermittent Windshield Wipers

Compact Spare Tire

Tires: P225/50r17 93v As

Body-colored Pwr Mirrors

Chrome Window Trim

Wheels: 17" X 7.5" Alloy

Body-colored Door Handles

Projector Beam Halogen Headlamps W/auto-off

Body-colored Bumpers

225/50vr17.0

ENTERTAINMENT FEATURES

160-watt Am/fm Stereo W/6-disc In-dash Cd Changer -inc: (6) Speakers, Radio Data System, Mp3/wma Playback, Usb Audio Interface, Auxiliary Input Jack, Speed-sensitive Volume Control

Integrated Rear Window Antenna

SAFETY FEATURES

4-wheel Anti-lock Brake System (abs) W/electronic Brake Distribution (ebd)

Brake Assist

Vehicle Stability Assist (vsa) W/traction Control

Advanced Compatibility Engineering (ace) Body Structure

Side-impact Door Beams

Daytime Running Lamps

Dual-stage, Multiple-threshold Front Airbags

Dual-chamber Front Side Airbags W/passenger-side Occupant Position Detection System

INTERIOR FEATURES

Front & Rear Side Curtain Airbags

3-point Seat Belts In All Seating Positions -inc: Front Automatic Tensioning System

Outboard Lower Anchors & Tethers For Children (latch)

Rear Center Child Seat Tether Anchor

Emergency Trunk Release

Tire Pressure Monitoring System

MECHANICAL FEATURES

Pwr Ventilated Front/solid Rear Disc Brakes

Chrome Exhaust Finisher

Active Noise Cancellation (anc)

Front-wheel

Double Wishbone Front Suspension

Drive-by-wire Throttle

Independent Multi-link Rear Suspension

Front Shock Tower Bar

Direct Ignition System

Engine: 2.4l 16-valve Dohc I-vtec I-4

Variable Pwr Rack & Pinion Steering

18.5gal. Fuel Tank

Transmission: 5-speed Manual W/od

Front & Rear Stabilizer Bars

RECALLS

Campaign No: 19V502000

Date	06/27/2019
Component	Air Bags
Summary	<p>honda (american honda motor co.) is recalling certain 2009-2014 acura tsx, 2011-2014 tsx sport wagon, 2010-2013 zdx, 2008-2012 honda accord, 2010-2011 accord crosstour, 2006-2011 civic and civic hybrid, 2008-2010 civic gx ngv, 2012-2015 crosstour, 2007-2011 cr-v, 2009-2013 fit, 2014 fit ev, 2010-2014 insight, and 2009-2015 pilot vehicles. the vehicles are equipped with passenger frontal air bag inflators assembled as a recall remedy part or replacement service part, that may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.</p>
Consequences	<p>an inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death.</p>
Remedy	<p>honda will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. the recall began august 12, 2019. owners may contact honda customer service at 1-888-234-2138. honda's numbers for this recall are f5f and q5e.</p>

Campaign No: 19V378000

Date	05/16/2019
Component	Air Bags

Campaign No: 19V502000

Summary	<p>honda (american honda motor co.) is recalling certain 2009-2014 acura tsx, 2011-2013 tsx sport wagon, and 2010-2012 zdx and 2008-2012 honda accord, 2010-2011 accord crosstour, 2006-2011 civic, civic hybrid and civic ngv, 2012-2014 crosstour, 2007-2011 cr-v, 2009-2013 fit, 2010-2013 insight, and 2009-2015 pilot vehicles. the front passenger air bag inflator may have been installed incorrectly during replacement.</p>
Consequences	<p>an incorrectly installed air bag inflator may not properly deploy the passenger frontal air bag in the event of a crash, increasing the risk of injury.</p>
Remedy	<p>honda will notify owners, and dealers will inspect the inflator installation and, if necessary, replace the passenger frontal air bag module assembly, free of charge. the recall began july 5, 2019. owners may contact honda customer service at 1-888-234-2138. honda's numbers for this recall are m4o, p4r, t4q, and w4p.</p>

Campaign No: 18V661000

Date	09/27/2018
Component	Air Bags
Summary	<p>honda (american honda motor co.) is recalling certain 2014 honda insight and acura tsx and tsx wagon, 2014-2015 honda crosstour and pilot vehicles nationwide, as well as certain 2014 honda fcx clarity and fit ev vehicles in florida, hawaii, puerto rico, texas, alabama, georgia, louisiana, mississippi, south carolina, california, american samoa, guam, the northern mariana islands (saipan) and the u.s. virgin islands. honda is also recalling certain 2011-2013 acura tsx, tsx wagon and zdx, honda crosstour, insight, fit and pilot vehicles, 2011-2012 honda accord and 2011 honda civic ngv, civic, civic hybrid and cr-v vehicles in arizona, arkansas, delaware, the district of columbia, illinois, indiana, kansas, kentucky, maryland, missouri, nebraska, nevada, new jersey, new mexico, north carolina, ohio, oklahoma, pennsylvania, tennessee, virginia and west virginia. lastly, honda is recalling certain 2010-2013 acura tsx and zdx, honda crosstour, fit, insight and pilot, 2011-2013 tsx wagon, 2010-2012 honda accord and 2010-2011 honda civic ngv, civic, civic hybrid and cr-v vehicles in alaska, colorado, connecticut, idaho, iowa, maine, massachusetts, michigan, minnesota, montana, new hampshire, new york, north dakota, oregon, rhode island, south dakota, utah, vermont, washington, wisconsin and wyoming. these vehicles are equipped with certain air bag air bag inflators assembled as part of the frontal air bag modules, and used as original equipment or replacement equipment (such as after a vehicle crash necessitating replacement of the original air bags), may explode due to propellant degradation occurring after long-term exposure to higher absolute humidity, temperature and temperature cycling.</p>
Consequences	<p>an inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death.</p>
Remedy	<p>honda will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. the recall began november 6, 2018. owners may contact honda customer service at 1-888-234-2138. honda's numbers for this recall are m2j and s2k.</p>

Campaign No: 18V268000

Date	04/26/2018
Component	Air Bags
Summary	<p>honda (american honda motor co.) is recalling certain 2003-2012 honda accord and pilot, 2010 accord crosstour, 2001-2011 civic, 2002-2011 cr-v, 2003-2004, 2006-2008 and 2011 element, 2007 and 2009-2013 fit, 2010-2012 insight, 2002-2004 odyssey, and 2012 ridgeline vehicles. the front passenger air bag may have been installed incorrectly during replacement.</p>
Consequences	<p>an incorrectly installed air bag may deploy improperly in the event of a crash, increasing the risk of injury.</p>
Remedy	<p>honda will notify owners, and dealers will inspect and, if necessary, replace the passenger frontal air bag module assembly, free of charge. the recall began june 22, 2018. owners may contact honda customer service at 1-888-234-2138. honda's numbers for this recall are k1p, and m1o.</p>

Campaign No: 18V042000

Date	01/09/2018
Component	Air Bags

Campaign No: 19V502000

Summary	honda (american honda motor co.) is recalling certain 2010-2013 acura tsx, zdx, honda accord crosstour, fit, insight and pilot vehicles, 2011-13 acura tsx sportswagon, 2010-2012 honda accord,, 2010-2011 honda civic, civic ngv, civic hybrid and cr-v vehicles and 2013 honda fcx clarity and fit ev vehicles ever registered in the states of alabama, california, florida, georgia, hawaii, louisiana, mississippi, south carolina, texas, puerto rico, american samoa, guam, the northern mariana islands (saipan), and the u.s. virgin islands or "zone a." additionally, honda is recalling certain 2010-2012 acura tsx, honda accord, accord crosstour, fit and pilot, 2010-2011 honda civic, civic ngv, civic hybrid and cr-v, and 2010 acura zdx and honda insight vehicles ever registered in the states of arizona, arkansas, delaware, district of columbia, illinois, indiana, kansas, kentucky, maryland, missouri, nebraska, nevada, new jersey, new mexico, north carolina, ohio, oklahoma, pennsylvania, tennessee, virginia, and west virginia or "zone b." unless included in zones a or b above, honda is recalling certain 2009 acura tsx, honda accord, civic, civic ngv, civic hybrid, cr-v, fit, and pilot vehicles ever registered in the states of alaska, colorado, connecticut, idaho, iowa, maine, massachusetts, michigan, minnesota, montana, new hampshire, new york, north dakota, oregon, rhode island, south dakota, utah, vermont, washington, wisconsin, and wyoming or "zone c." these vehicles are equipped with certain air bag inflators assembled as part of the frontal air bag modules, and used as original equipment or replacement equipment (such as after a vehicle crash necessitating replacement of the original air bags), may explode due to propellant degradation occurring after long-term exposure to higher absolute humidity, temperature and temperature cycling.
Consequences	an inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death.
Remedy	honda will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. the recall began february 16, 2018. owners may contact honda customer service at 1-888-234-2138. honda's numbers for this recall are b0k and l0j.

Campaign No: 17V545000

Date	08/31/2017
Component	Air Bags
Summary	honda (american honda motor co.) is recalling certain 2008-2012 accord, 2010-2012 accord crosstour, 2006-2011 civic, 2007-2011 cr-v, 2009-2012 fit and pilot, 2010-2012 insight, and 2009-2012 acura tsx vehicles that received replacement passenger frontal air bag inflators. one dealership may have incorrectly installed the replacement air bag inflators.
Consequences	in the event of a crash, an incorrectly installed passenger frontal air bag inflator may deploy the air bag improperly, increasing the risk of injury.
Remedy	honda will notify owners, and dealers will replace the passenger frontal air bag module assembly, free of charge. the recall began october 30, 2017. owners may contact honda customer service at 1-888-234-2138. honda's numbers for this recall are o07, y0a, n06, g05, m04, y01, and o09.

Campaign No: 17V030000

Date	01/10/2017
Component	Air Bags
Summary	honda (american honda motor co.) is recalling certain 2009-2012 acura tsx, 2011-2012 acura tsx wagon, 2010-2012 acura zdx, 2008-2012 honda accord, 2010-2012 honda accord crosstour and honda insight, 2009-2012 honda fit, 2009-2012 pilot, 2007-2011 honda cr-v, 2012 honda fcx clarity and 2006-2011 honda civic, civic hybrid, civic ngv vehicles originally sold, or ever registered, in alabama, california, florida, georgia, hawaii, louisiana, mississippi, south carolina, texas, puerto rico, american samoa, guam, the northern mariana islands (saipan), and the u.s. virgin islands, or "zone a." additionally, if not included in "zone a" above, honda is recalling certain 2009 acura tsx, honda fit and pilot, 2008-2009 honda accord, 2006-2009 civic, civic hybrid and civic ngv, and 2007-2009 honda cr-v vehicles originally sold, or ever registered, in arizona, arkansas, delaware, district of columbia, illinois, indiana, kansas, kentucky, maryland, missouri, nebraska, nevada, new jersey, new mexico, north carolina, ohio, oklahoma, pennsylvania, tennessee, virginia, and west virginia, or "zone b." additionally, if not included in "zone b" above, honda is recalling certain 2008 honda accord, 2006-2008 honda civic, civic hybrid and civic ngv and 2007-2008 honda cr-v vehicles originally sold, or ever registered, in alaska, colorado, connecticut, idaho, iowa, maine, massachusetts, michigan, minnesota, montana, new hampshire, new york, north dakota, oregon, rhode island, south dakota, utah, vermont, washington, wisconsin, and wyoming. these vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. in the event of a crash necessitating deployment of the front air bags, these inflators may rupture due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Campaign No: 19V502000

Consequences	an inflator rupture may result in metal fragments striking the vehicle occupants resulting in serious injury or death.
Remedy	honda will notify owners, and dealers will replace the front passenger side air bag inflator, free of charge. the manufacturer has mailed an interim notification, and will send a second notification when parts are available. owners may contact honda customer service at 1-888-234-2138. honda's numbers for this recall are ke1 and ke2.

Campaign No: 12V030000

Date	02/01/2012
Component	Air Bags
Summary	honda is recalling certain model year 2012 accord and crosstour vehicles. the driver-side or passenger-side side curtain airbag inflator may not have been manufactured according to correct specifications.
Consequences	in the event of a crash, the side curtain airbag may fail to deploy, increasing the risk of injury.
Remedy	honda will replace the driver's side or passenger's side side curtain airbag as needed free of charge. the safety recall began on february 24, 2012. owners may contact honda customer service at 1-800-999-1009.

This REDLINE USED AUTO PARTS Report is based only on information acquirable by REDLINE USED AUTO PARTS as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to REDLINE USED AUTO PARTS. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2023 REDLINE USED AUTO PARTS. All Rights Reserved.